



Manual book for Wood Briquette machine

Made in China



SHENYANG C&A MACHINERY

FOREWORD


- 1. INTRODUCING FOR THE MACHINE
- 2. MAIN PARTS
- 3. OPERATION
- 4. MANINTANACE
- 5. FAILURE AND SOLVEING
- 6. MAIN DATA

1. INTRODUCING FOR THE MACHINE

The machine mainly use the sawdust, branch, rice hull, peanut hull, dregs of coffee, grain straw etc , which they are grinded , through higher temperature and pressure to heat them, make them stick for the fuel .

The raw materials should be less than 5mm, the moisture is 8 % orso.

2. Main parts



3. OPERATION

A. check all screw belt for guantee them normal not loosen ,check if lubricate into the gears ,etc.

- B. check the electrical broad for contacting right.
- c. adjust the temperature meter to 280 degrees, to heat ,till it automatically stop ,then put the materials into hopper ,slowly the

stick briquette would be out.

Only working normally for 30 mins orso, which show the operating successfuly.


- D. the length of stick could be adjusted by hand according to the requires at the local market.
- E. make not any materials inner hopper before stoping the machine, and to reversing for one min ,let the materials out from the propeller .

4. Maintenance for the Propeller

If show the following question ,the propeller should be repaired.

- 1.the speed of producing the stick
- 2.the raw materials is normal, but the shaft is jammed now and then.
- 3.the stick is ok, but it could not contact one good length.
- 4.the speed of producing, but it is loosen, lower density
- 5.the face part is less then 4mm for the frower of propeller
- 6. the dia of inner of final stick is less then 15mm
- 7.the screw parts is wore out or destroyed

Repairing the propeller



- 1. pre-heating the part welded for 350 degrees.
- 2.use the direct current welding machine, with casting, cineration, tungstenic alloy welding rod (hardness HRA77) (melting point 1600 1700 degree).
- 3.one lay by one layer weld on the part wore ,after welding one layer, to remove the welding dregs, then weld the second layer. The thickness welding is more 1-2mm than the normal requires, the

propeller welding not promit dregs, air hole etc.


4.cool the propeller

After welding, put the part welded into the dry calces or plant ash for cooling.

5. when cooling to under 50 degrees take out . Polish it on the grinding wheel slowly ,probid to use the water or the other liquid .

6.when polishing it ,the forward of screw part ,at 360 degree periodic angle ,its forward angle slowly add from 2 degree to 22degree $+_1$ 1.5 degree at the tip part . Note,it should smoothly .

According to the following map ,if the shaft wore is more than 6mm, repair it as it.



A. When pre-heating to 350 degrees ,at the length 105mm ,steady welding lay by lay with carbal welding rods, which is more 1-2mm then the size of the map.

B. cooling it as the before.

Note:

- 1. tighten the screw of heating collar, and the 3 pcs thimble inner of mounting sleeve.
- 2. after stoping ,then to before opeing again ,the temperature of heating collar should be 350 degrees .
- 3. the volvage is 360 v orso.
- 4. if propeller could not run, stop quickly the machine and conversely the running to let the materials be out from the hopper, add 20 degrees than the before confirmed then open it again.
- 5. Forbid standing any person before the outer.
- 6.forbid any stone and iron into the hopper ,or quickly stop it to

remove it.

7.keep the dry for the electrical parts, before stoping the machine ,pls cut the power in advance.

- 8. lunricate all parts each month.
- 9. the machine is contacted to the ground normally .

5. FAILURE AND SOLVEING

No	phenomenon	reason	solve		
1	Lamp is not light	a.not contact to the power	a.contact to the power		
		b.fuse blowout	b.change the fuse		
		c.the lamp is destroied	c.change one		
2	The motor not	a.the volvage is lower	a.change the button		
	work	b.2 phases work	b.contact the electrical wire		
		c.voltage and hz is not accord	c.check it		
3.	The temperature	a. voltage is low	a. check the voltage		
	is slow and not	b. heating collar is destoried	b. change the heating collar		
	up to 350 degrees	c. type of hearing collar is not	c. choose the right type		
		correct			
4	The motor is heat	a. load is big	a. check it according to No 5		
		b. 2 phases work	b. check the fuse ,button,knife		
		c. Bearings is destroyed	switch		
		d. Wind funnel is jam	c. change the bearings		
		e. High temperature near it	d. clear the impurity		
		f. The volvage is not jarless	e. reduce the temperature		
		g. short circuit	f. adjust the volvage		
			g. check and solve the matter		
5	The stick is not	a. wet materials	a. dry the materials		
	out	b. the temperature is low	b. add the temperature		
		c. screw groove nip the materials	c. repair the propeller,clear the		
		d. the stagger for the groove of	impurity		
		inner sleeve and heating collar	d. assamble the inner sleeve of		
		e. low volvage	heating collar		
		f. groove of the inner sleeve is	e. check the volvage		
		wore out	f. change the inner sleeve		
		g. sleeve of heating collar is	g. change the inner sleeve		
		destroyed	h. repair the propeller		
		h. propeller is wore out			

6	The stick is not	a.	wet materials	a.	dry the raw materials	
	2450549000 0009000000 F000 4444000000			3800		
	complete	b.	the stagger for the groove of	b.	assamble the inner sleeve	
			inner sleeve and heating collar	c.	reduce the temperature	
		c.	high temperature	d.	repair the angle	
		d.	the angle of propeller is less e. assamble the		assamble the thermocouple	
			than 20 degrees	f.	check the circuit of heating	
		e.	thermocouple is not assembled		collar	
			well or wrong place	g.	repair the angle of propeller	
		f.	short circuit of heating collar		for the No 4	
		g.	oil is more of the materials	h.	tighten the belts	
		h.	the belts is loosen			
7	Steams is out	a.	wetter raw materials	a.	dry the materials	
	from the hopper	b.	inner sleeve of bracket is wore	b.	repair the inner sleeve	
	and bumping		out	C.	same as b	
		c.	inner sleeve of heating collar is	d.	same as b	
			wore out	e.	repair the propeller	
		d.	the angle of propeller is not			
3			cccord			

6. Main data

Model	ZBJ-III ZBJ-II		ZBJ-I			
Output kg/h	750-1000	200-300	150-200			
Motor Power	30	15	11kw			
(kw)						
Electric heater	3*1.5	3*1.5	3*1.5			
(kw)						
Size of	Ø50-100, length	Ø45-55, length	Ø45-55,length			
products (mm)	> 50mm	> 50mm	> 50mm			
Size (mm)		1680*550*1280	1650*530*1250			
Weight (kg)	910 780		720			
Consumptation	< 100kwh/t					
Density of						
product	1.1-1.3t/m3					
Heating	4400-5000kcal/kg					
quantity						

• Note: spare parts

1. Mounting Inner-Sleeve

2 Forming Cylinder

2. Propeller

3. Heating Collar

The others' machine matched

Wood crusher



9FH- Branch Crusher

BG- Straw Crusher

Introduce

9FH system crusher could crush the small diameter tree branch, less than 30mm, and BG system could crush the big diameter.

Mata

Item	BG-10	BG-20	9FH-36	9FH- 4 0	9FH-60
Capacity(kg/h)	350-650	750-1000	100	150-200	200-250
Diameter of feeding material (mm)	<=ø10	<=ø20	<=ø30	<=ø 4 0	<=ø60
Max. size of	Ø5 * 5	Ø5 * 5	Ø1 * 3	Ø1 * 3	Ø1 * 3

crush (mm)					
Motor(kw)	7.5 - 11kw	15-18.5k w	3-4	7.5-11	11-15
Overall dimension (cm)	180*70 *80	230*100 *1 4 0	70*48*95	75*55*115	

Pipe Dryer for sawdust

It is necessary for man-made briquetting line ,even the peanut shell and rice hull dried normally said, which is also required to dry them , only this they could meet the needs for making the briquette stick . It produce the high temperature funnel-air inner of the furnace of

dryer ,with the waste materials or gas born ,then make the raw materials (sawdust ,etc) contact to the funnel-air directly, to rid off the moisture of raw materials to less than 12% .so it could meet the requires of making the briquette stick .

The requires of raw materials : length <5 mm,dia

<3mm, water > 12%



HGJ Flash Dryer

Model	Capacity (Moisture:40%) (kg /hour)	materials Size of feeding (Diameter)	Temperature of Hot Air	Power (kw)	Installing size (m)	Dia. of main pipe
HGJ-I	300-500	< 20mm	180~250℃	4	20*0.85*2.2	300 mm
HGJ-II	600-800	< 20mm	180~250℃	5.5	30*0.85*2.5	350 mm
HGJ-III	1000-1500	< 20mm	180~250℃	7.5-11		400 mm